

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Sutter Maintenance Yard Hamilton Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River Hamilton Bend	Right	3.39	03/18/2020 03/18/2020	Sterling York

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Operations & Maintenance Manuals			o	
				o	
DWR ID	DWR_ST0005_01_s_2013_7				
Comment Code					
Inspector Comment					
O&M manual is located at the Sutter Maintenance Yard.					

No Photos

LM Start		Rating **	A	Issue No.	8
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Emergency Supplies & Equipment			o	
				o	
DWR ID	DWR_ST0005_01_s_2013_8				
Comment Code					
Inspector Comment					
Emergency supplies and equipment are stored at the Sutter Maintenance Yard.					

No Photos

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Flood Preparedness & Training			o	
				o	
DWR ID	DWR_ST0005_01_s_2013_9				
Comment Code					
Inspector Comment					
Sutter Maintenance Yard employees attend the annual Flood Fight class put on by DWR inspectors.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Sutter Maintenance Yard Hamilton Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River Hamilton Bend	Right	3.39	03/18/2020 03/18/2020	Sterling York

LM Start	0.01	Rating **	A	Issue No.	3
LM End	1.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.439776 °	39.456841 °	
			-121.641456 °	-121.639320 °	
DWR ID	DWR_ST0005_01_s_2020_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The annual vegetation is well maintained in this section, Spring 2020.					

Photo 1 of 1 : SP_2020_ST0005_289_3_20200327_00012.jpg



View looking upstream landside at the well maintained annual vegetation, Spring 2020.

LM Start	0.01	Rating **	A	Issue No.	5
LM End	1.22	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.439776 °	39.456842 °	
			-121.641457 °	-121.639320 °	
DWR ID	DWR_ST0005_01_s_2020_5				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The annual vegetation is well maintained in this section, Spring 2020.					

Photo 1 of 1 : SP_2020_ST0005_289_5_20200327_00013.jpg



View looking upstream waterside at the well maintained annual vegetation, Spring 2020.

LM Start	0.19	Rating **	M	Issue No.	15
LM End	0.19	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.442435 °	39.442435 °	
			-121.641760 °	-121.641760 °	
DWR ID	DWR_ST0005_01_s_2015_15				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Sutter Maintenance Yard Hamilton Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River Hamilton Bend	Right	3.39	03/18/2020 03/18/2020	Sterling York

LM Start	0.70	Rating **	M	Issue No.	16
LM End	0.70	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.449623 °	39.449623 °
				-121.640940 °	-121.640940 °
DWR ID	DWR_ST0005_01_s_2017_16				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	0.71	Rating **	M	Issue No.	12
LM End	0.91	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.449757 °	39.452614 °
				-121.640886 °	-121.640284 °
DWR ID	DWR_ST0005_01_s_2020_12				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Trees that are less than 4" in diameter need to be removed, Spring 2020.					

Photo 1 of 1 : SP_2020_ST0005_289_12_20200327_00014.jpg



View looking upstream waterside at trees that are less than 4" in diameter that need to be removed, Spring 2020.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Sutter Maintenance Yard Hamilton Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River Hamilton Bend	Right	3.39	03/18/2020 03/18/2020	Sterling York

LM Start	0.97	Rating **	M	Issue No.	10
LM End	0.97	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		39.453512 °	39.453512 °	
			-121.640272 °	-121.640272 °	
DWR ID	DWR_ST0005_01_s_2020_10				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Trim tree for visibility, Spring 2020.					

Photo 1 of 1 : SP_2020_ST0005_289_10_20200327_00015.jpg



View looking waterside at a tree hat needs to be trimmed for visibility, Spring 2020.

LM Start	1.48	Rating **	U	Issue No.	18
LM End	1.99	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		39.458053 °	39.461949 °	
			-121.636300 °	-121.629563 °	
DWR ID	DWR_ST0005_01_s_2017_18				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Trim/Thin Trees from Levee Mile 1.48 to 1.99. The LMA does not maintain the levee from Levee Mile 1.38 to 3.39.					

Photo 1 of 1 : SP_2020_ST0005_289_18_20200227_00005.jpg



View looking upstream of thick trees and vegetation blocking visibility on waterside.

LM Start	1.48	Rating **	U	Issue No.	11
LM End	3.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		39.458055 °	39.470312 °	
			-121.636300 °	-121.609242 °	
DWR ID	DWR_ST0005_01_s_2017_11				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Trim/Thin Trees from Levee Mile 1.48 to 3.25. The LMA does not maintain the levee from Levee Mile 1.38 to 3.39.					

Photo 1 of 1 : SP_2020_ST0005_289_11_20200227_00003.jpg



View looking upstream of thick trees blocking visibility on landside.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Sutter Maintenance Yard Hamilton Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River Hamilton Bend	Right	3.39	03/18/2020 03/18/2020	Sterling York

LM Start	1.50	Rating **	U	Issue No.	17
LM End	1.96	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.458131 °	39.461634 °	
			-121.635916 °	-121.629926 °	
DWR ID	DWR_ST0005_01_f_2017_17				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Maintain annual grasses from Levee Mile 1.50 to 1.96. The LMA does not maintain the levee from Levee Mile 1.38 to 3.39.					

Photo 1 of 1 : SP_2020_ST0005_289_17_20200227_00004.jpg



View looking upstream waterside of annual grasses that need to be maintained.

LM Start	1.50	Rating **	U	Issue No.	6
LM End	2.63	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.458132 °	39.466025 °	
			-121.635914 °	-121.618972 °	
DWR ID	DWR_ST0005_01_f_2016_6				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Blackberries covering slope from Levee Mile 1.50 to 2.63. The LMA does not maintain the levee from Levee Mile 1.38 to 3.39.					

Photo 1 of 1 : SP_2020_ST0005_289_6_20200227_00002.jpg



View looking upstream landside of blackberries that are covering the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Sutter Maintenance Yard Hamilton Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River Hamilton Bend	Right	3.39	03/18/2020 03/18/2020	Sterling York

LM Start	3.23	Rating **	U	Issue No.	4
LM End	3.27	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		39.470063 °	39.470558 °	
			-121.609264 °	-121.609215 °	
DWR ID	DWR_ST0005_01_s_2013_4				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Small trees 4" in diameter at chest height should be removed before they get too big from Levee Mile 3.23 to 3.27. Levee Mile 1.38 to 3.39 has never been maintained by the LMA.					

Photo 1 of 1 : SP_2020_ST0005_289_4_20200227_00001.jpg



View looking upstream waterside of small trees 4" in diameter at chest height should be removed before they get too big.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---